



#### **PROJECT INFORMATION**

**Building Type:** Healthcare, Behavioral Facility

Facilities Director: Robert Kimmy, Stewart Marchman Behavioral Unity

**Contractor:** Charles Jones, Service 1st Port Orange, Florida

**Distributor:** Mark Graham Baker Distribution Holly Hill, Florida

## **BLUEPRINT**

# STEWART MARCHMAN BEHAVIORAL UNIT DAYTONA BEACH, FLORIDA



#### **Challenge:**

Rooms were too hot or too cold, no zoning was offered with the existing system, and staff complaints of being uncomfortable. Most rooms were on interior walls where condensate pumps were used on all the fan coils.

### **The Solution:**

Installing a Daikin Multi-Split and Single Split RA system.

The Stewart Marchman Behavioral facility had a 7.5 ton DX split system ducted to multiple areas including a number of offices and intake rooms. Due to the nature of the business, the load was constantly shifting from one area to another. The facilities crew were constantly called upon for service of areas either too hot or too cold. The Daikin system gives added zoning in those troublesome spots.

With the addition of the 5 fan coils in the problematic areas, staff complaints have all but disappeared and the building is more comfortable for the staff and patients.



"I would like to tell you how much our staff likes your product and how much it has helped with complaints about being too hot or too cold. It has been such a blessing to the facilities department with lowering the calls that we have had to go out on. We are remodeling another site within our company and I am proud to announce that we are planning on using the Daikin products in this project as well."

> Robert Kimmy, Facilities Director Stewart Marchman Behavioral Unit

# BLUEPRINT STEWART MARCHMAN BEHAVIORAL UNIT DAYTONA BEACH, FLORIDA

### **FIND OUT MORE ABOUT DAIKIN VRV.** Contact your local dealer or manufacturer's representative.

### Additional information

Before purchasing this appliance, read important information about its estimated annual energy consumption, yearly operating cost, or energy efficiency rating that is available from your retailer.

#### DAIKIN EQUIPMENT

- 4 CTXS09GVJU Wall Mounted Indoor Units
- 1 FTXS18HVJU Wall Mounted Indoor Unit
- 1 4MXS32GVJU Outdoor Unit
- 1 RXS18DVJU Outdoor Unit

Actual savings and costs will vary. Cost and savings statements are applicable solely to the installation indicated. For additional information please contact the installing contractor, distributor or factory representatives.

